

ILLINOIS VALLEY COMMUNITY COLLEGE

COURSE OUTLINE

DIVISION: Workforce Development

COURSE: WLD 2208 OAW Oxy, Plasma Cutting, Air

Carbon Arc

2020	
2	
None	
∠ Lecture	1 Contact Hours (1 contact = 1 credit hour)
Seminar	0 Contact Hours (1 contact = 1 credit hour)
⊠ Lab	2 Contact Hours (2-3 contact = 1 credit hour
Clinical	0 Contact Hours (3 contact = 1 credit hour)
Online	
Blended	
⊠ Spring	⊠ Summer
	None Lecture Seminar Lab Clinical Online Blended

IAI Equivalent – Only for Transfer Courses-go to http://www.itransfer.org:

CATALOG DESCRIPTION:

This course includes the theory, safety and operation of oxyacetylene cutting, plasma cutting, and carbon arc use.

GENERAL EDUCATION GOALS ADDRESSED

[See last page for Course Competency/Assessment Methods Matrix.]

Upon completion of the course, the student will be able:

[Choose up to three goals that will be formally assessed in this course.]

🗓 To apply analytical and problem solving skills to personal, social, and professional	
issues and situations.	
To communicate successfully, both orally and in writing, to a variety of audiences.	
To construct a critical awareness of and appreciation for diversity.	
To understand and use technology effectively and to understand its impact on the	
individual and society.	
To develop interpersonal capacity.	
oxtimes To recognize what it means to act ethically and responsibly as an individual and as	3 6
member of society.	
To recognize what it means to develop and maintain a healthy lifestyle in terms of	
mind, body, and spirit.	
To connect learning to life.	

EXPECTED LEARNING OUTCOMES AND RELATED COMPETENCIES:

[Outcomes related to course specific goals. See last page for more information.]

Upon completion of the course, the student will be able to:

- 1. Safe use of all equipment as well as all safety guidelines will be discussed and utilized.
- 2. Understand and demonstrate safe work practices in the welding shop in regards to oxyacetylene torch cutting equipment.
- 3. Understand and demonstrate safe work practices in the welding shop in regards to plasma cutting equipment.
- 4. Understand and demonstrate safe work practices in the welding shop in regards to carbon arc gouging and cutting.
- 5. Demonstrate the ability to cut mild steel with an oxyacetylene torch, in flat- straight and round cuts, bevel cutting, pipe- straight, round and bevel cuts.
- 6. Demonstrate the ability to cut mild steel with plasma cutting torch in flat- straight and round cuts, bevel cutting, pipe- straight, round and bevel cuts.
- 7. Demonstrate the ability to set up and use carbon arc equipment with mild steel, to gouge and bevel in both flat plate and pipe.
- 8. Demonstrate the ability to conduct a Visual Examination of these cuts and bevels to AWS criteria.

MAPPING LEARNING OUTCOMES TO GENERAL EDUCATION GOALS

[For each of the goals selected above, indicate which outcomes align with the goal.]

Goals	Outcomes
First Goal	
To apply analytical and problem solving skills to personal, social, and professional issues and situations.	1,2,3,4,5,6,7

Second Goal	
To understand and use technology effectively and to understand its impact on the individual and society.	1,2,3,4,5,6,7
Third Goal	
To recognize what it means to act ethically and responsibly as an individual and as a member of society.	1,2,3,4,5,6,7

COURSE TOPICS AND CONTENT REQUIREMENTS:

Shop safety
Basic Printreading
Oxyfuel gas cutting equipment
Using Oxyfuel cutting equipment
Plasma arc cutting equipment
Using plasma arc cutting equipment
Air carbon arc cutting equipment
Using air carbon arc cutting equipment

INSTRUCTIONAL METHODS:

Classroom lecture, weld lab hands-on instruction

INSTRUCTIONAL MATERIALS:

Welding textbook and workbook Welded examples Selected handouts Videos

STUDENT REQUIREMENTS AND METHODS OF EVALUATION:

Modern Welding textbook and workbook, G-W, 12th edition
All appropriate personal protective equipment to safely perform in the welding lab
Students will be graded with examinations
Visual inspection of cut specimens
Visual inspection of final cut specimens

The following grading scale will be used:

A= 90-100

B = 80-89

C = 70-79

D= 60-69

F= 0-59

OTHER REFERENCES

Lincoln Electric Welding technology center Hobart institute of Welding technology Course Competency/Assessment Methods Matrix

(Dept/# Course Name)	Assessment Options																															
For each competency/outcome place an "X" below the method of assessment to be used.	Assessment of Student Learning	Article Review	Case Studies	Group Projects	Lab Work	Oral Presentations	Pre-Post Tests	Quizzes	Written Exams	Artifact Self Reflection of Growth	Capstone Projects	Comprehensive Written Exit Exam	Course Embedded Questions	Multi-Media Projects	Observation	Writing Samples	ion	Real World Projects	Reflective Journals	Applied Application (skills) Test	Oral Exit Interviews	Accreditation Reviews/Reports	Advisory Council Feedback	Employer Surveys	Graduate Surveys	Internship/Practicum /Site Supervisor Evaluation	Licensing Exam	In Class Feedback	Simulation	Interview	Written Report	Assignment
Assessment Measures – Are direct or indirect as indicated. List competencies/outcomes below.	Direct/ Indirect	۵	D	۵	D	D	D	۵	D	D	D	D	D	D	D	D	۵	D	D	D	_	_		_	D	D						
Safe use of all equipment as well as all safety guidelines will be discussed and utilized					X			Х	X						X			X		X												
Understand and demonstrate safe work practices in the welding shop in regards to oxyacetylene torch cutting equipment					Х			Х	X						Х			X		X												
Understand and demonstrate safe work practices in the welding shop in regards to plasma cutting equipment					Χ			Х	X						X			X		X												

Understand and demonstrate safe work practices in the welding shop in regards to carbon		X	X Z	×			X		X	X						
arc gouging and cutting Demonstrate the ability to cut mild steel with an oxyacetylene torch, in flat- straight and round cuts, bevel cutting, pipe- straight, round and bevel cuts.		X	X 2	×			X		×	X						
Demonstrate the ability to cut mild steel with plasma cutting torch in flat- straight and round cuts, bevel cutting, pipe- straight, round and bevel cuts.		X	× 2	x			X		X	Х						
Demonstrate the ability to set up and use carbon arc equipment with mild steel, to gouge and bevel in both flat plate and pipe		X	X Z	x			X	2	X	X						
Demonstrate the ability to conduct a Visual Examination of these cuts and bevels to AWS criteria.		X	x 2	X			X	2	X	Х						